



Syscal R2 check list

Device

Syscal switch (Tx and Rx fully charged)
USB Cable with Syscal Plug
Syscal user's manual
[Safety instruction leaflet](#)

Softs

CD IRIS Instruments with USB Driver
RES2/3DINV Dongle
Laptop with [Prosys](#) installed

Tools

Security Pack
Electrode Tester
Battery Tester

Accessories

Battery chargers + adapters if necessary
12V External Battery fully charged
External Battery Cable
(Red & Black) Alligator Clip (Red & Black)
Stainless steel Electrodes or Unpolarizable Electrodes
Cord Clip (3 + number of channels + extras)
Cables (orange or yellow)
Reels of cable (1 for pole-dipole, 2 for pole-pole)
Measuring tape (non-metallic)
GPS
Hammer
Voltmeter with two 1m cables
Salted water + bentonite

250W DC/DC converter

12V External Battery fully charged
External Battery Cable (Red & Black)
Alligator Clip (Red & Black)
converter user's manual

1200W AC/DC converter

Power cord

Extension cord

converter user's manual

www.iris-instruments.com