



IRIS instruments

Syscal Switch checklist

Device	
	Syscal standard (Tx and Rx fully charged)
	USB Cable with Syscal Plug
	Syscal user's manual
Softs	
	CD IRIS Instruments with USB Driver
	RES2/3DINV Dongle
	Laptop with Electre Pro + Prosys installed
Accessories	
	Battery chargers + adapters if necessary
	12V External Battery fully charged
	External Battery Cable (Red & Black)
	Alligator Clip (Red & Black)
	Stainless steel Electrodes or Unpolarizable Electrodes
	Cord Clip (3 + number of channels + extras)
	Cables (orange or yellow)
	Connecting boxes (if necessary)
	Reels of cable (1 for pole-dipole, 2 for pole-pole)
	Pole-Pole optimization cable (for pole-dipole or pole-pole)
	Measuring tape (non-metallic) or/and GPS
	Hammer
	Voltmeter with two 1m cables
	Salted water + bentonite