



IRIS instruments

TIPIX checklist (1/4)

Device	
	TIPIX
	Power cable
	TIPIX user's manual
Accessories	
	Power generator
	Fuel
	Stainless steel Electrodes (large)
	Reels of cable
	Measuring tape (non-metallic) and/or GPS
	Hammer
	Voltmeter with two 1m cables
	Salted water + bentonite

VIP checklist (2/4)

Device	
	VIP
	Power cable
	RS232 link
	VIP user's manual
Accessories	
	Programming key
	Lamp extraction kit
	Power generator
	Fuel
	Stainless steel Electrodes (large)
	Reels of cable
	Measuring tape (non-metallic) and/or GPS
	Hammer
	Voltmeter with two 1m cables
	Salted water + bentonite

Elrec checklist (3/4)

Device	
	Elrec device
	USB Cable with Syscal Plug
	Elrec user's manual
Softs	
	CD IRIS Instruments with USB Driver
	RES2/3DINV Dongle
	Laptop with Electre Pro + Prosys installed
Accessories	
	Battery chargers + adapters if necessary
	12V External Battery fully charged
	External Battery Cable (Red & Black)
	Alligator Clip (Red & Black)
	Stainless steel Electrodes or Unpolarizable Electrodes (number of channels +1 extras)
	Cord Clip (number of channels + 1 + extras)
	Reels of cable (number of channels + 1 + extras)
	Measuring tape (non-metallic) or/and GPS
	Hammer
	Voltmeter with two 1m cables
	Salted water + bentonite

Fullwavers checklist (4/4)

Device	
	V - Fullwavers
	I - Fullwavers
	Fullwavers user's manual
Softs	
	CD IRIS Instruments with USB Driver
	RES2/3DINV Dongle
	USB stick 8Gb
	Laptop with Fullwaveviewer + Prosys installed
Accessories	
	Battery chargers + adapters if necessary
	12V External Batteries fully charged (if necessary)
	External Battery Cable (if necessary)
	Alligator Clip (if necessary)
	Stainless steel Electrodes or Unpolarizable Electrodes (3 per fullwaver + extra)
	Cord Clip (3 per fullwaver + extra)
	Reels of cable (3 per fullwaver + extra)
	Measuring tape (non-metallic) and/or GPS
	Hammer
	Voltmeter with two 1m cables