



IRIS instruments

TIPIX checklist

Device	
	TIPIX
	Power cable
	TIPIX user's manual
Accessories	
	Power generator
	Fuel
	Stainless steel Electrodes (large)
	Reels of cable
	Measuring tape (non-metallic) and/or GPS
	Hammer
	Voltmeter with two 1m cables
	Salted water + bentonite